

# Ultra Purge<sup>™</sup> HT+ Ready-to-Use Glass-Filled Purging Compound

#### **Benefits**

- High efficiency
- Rapid cleaning effect
- Easy to use
- Operator and equipment safe
- Wide application range

#### Description

Ultra Purge<sup>™</sup> HT+ is a ready-to-use glass-filled purging compound. It can be used for cleaning in injection molding, and extrusion applications. Ultra Purge<sup>™</sup> HT+ can also be used for the cleaning of screw, barrel and nozzle, of injection molding machines processing thermoplastic resins. The purging concentrate consists of highly efficient cleaning additives.

### Ultra Purge<sup>™</sup> HT+ can be used at processing temperatures from 250 °C (482 °F) to 400 °C (752 °F).

The purging compound is especially recommended for color and material change as well as for the removal of black spots, carbon residues.

Ultra Purge<sup>™</sup> HT+ is suitable for following thermoplastic resins:

Resin	Suitable
Amorphous resins	
Crystalline resins	
PA, POM	
PET	
Polyolefins	
PS	
TPE-TPR	
High-temperature engineering resins	++
PVC	
TPU	
Transparent polyamides, CA, CAB, when	
switching from any resin to PMMA	
When switching from any resin to PC	
When switching from any resin to PMMA	

#### Typical Properties

Appearance

Translucent yellow granules

#### **Special Notes**

- Do not use on mirror polished surfaces.
- Do not use more than recommended quantities of Ultra Purge<sup>™</sup> per cleaning.
- Do not increase temperatures when dealing with thermo-sensitive resins or additives.
- Do not use Ultra Purge<sup>™</sup> outside its working temperature range.

#### Application

This document is a general description on how to use Ultra Purge<sup>™</sup>. Request your customized instructions by contacting your nearest sales office or local distributor.

Please read carefully the SDS before using Ultra Purge<sup>™</sup>.

We recommend the following cleaning procedures.





Chem-Trend L.P. | 1445 W. McPherson Park | Howell, Michigan Tel 517.546.4520 | U.S./Canada: 800-727-7730 | Fax: 517-548-5370 | ChemTrend.com



# Ultra Purge<sup>™</sup> HT+ Ready-to-Use Glass-Filled Purging Compound

#### Cleaning of Screw and Barrel - Injection Molding -Material Change- DIFFERENT Temperatures:

- 1. Move the injection unit to the back position and manually remove all possible contaminants in the hopper/mixer/filters.
- 2. Make sure the barrel is empty when adding Ultra Purge<sup>™</sup> HT+ in the machine.
- Set screw rotation to maximum allowed speed. З.
- 4.
- Set shot size to 80% of maximum shot size. Add Ultra Purge<sup>™</sup> HT+ (at least 1 barrel capacity). Keep purging with Ultra Purge<sup>™</sup> HT+ until previous 5. resin is removed and empty the barrel from Ultra Purge<sup>™</sup> HT+.
- 6. Set the machine to the working temperature of the resin you are going to proceed (see next steps). If the cooling/heating time is greater than 5 minutes, add half barrel capacity of Ultra Purge<sup>™</sup> HT+ every 5 minutes and make sure to purge the barrel empty every time you purge. Do not use Ultra Purge<sup>™</sup> HT+ at a temperature lower
- than 250 °C/482 °F. 7. Add the next production resin when at desired
- temperature and begin normal production. If contamination persists repeat steps. 8. \* Please note, Ultra Purge<sup>™</sup> HT+ may turn reddish in color after being processed. This is normal part of the cleaning process.

#### Cleaning of Screw and Barrel - Injection Molding-Material Change- SAME Temperature:

- Move the injection unit to the back position and 1. manually remove all possible contaminants in the hopper/mixer/filters.
- Make sure the barrel is empty when adding Ultra 2. Purge<sup>™</sup> HT+ in the machine.
- З. Set screw rotation to maximum allowed speed.
- 4.
- Set shot size to 80% of maximum shot size. Add Ultra Purge<sup>™</sup> HT+ (at least 1 barrel capacity). 5.
- Make injections until Ultra Purge<sup>™</sup> HT+ is used up 6. and load the next production resin directly after.
- 7. Keep making injections until all remnants of Ultra Purge<sup>™</sup> HT+ have been displaced from the machine.
- Begin normal production. 8.
- If contamination persists repeat steps. \* Please note, Ultra Purge<sup>™</sup> HT+ may turn reddish in 9. color after being processed. This is normal part of the cleaning process.

#### Cleaning Screw and Barrel – Extruder – Material Change – DIFFERENT Temperatures:

- 1. Make sure the barrel is empty when adding Ultra Purge<sup>™</sup> HT+ in the machine.
- We recommend removing the finest layer of the 2. screen pack. Make sure that the pressure or torque force remains within safety limits when running Ultra Purge<sup>™</sup>.
- Add Ultra Purge<sup>™</sup> HT+ (at least 1.5 times the 3. extruder barrel capacity).
- Extrude at high speed until the Ultra Purge<sup>™</sup> HT+ is 4. used up and empty the barrel.
- 5. Set the machine to the working temperature of the resin you are going to proceed (see next steps). If the cooling/heating time is greater than 5 minutes, add half barrel capacity of Ultra Purge<sup>™</sup> HT+ every 5 minutes and make sure to purge the barrel empty every time you purge. Do not use Ultra Purge<sup>™</sup> HT+ at a temperature lower than 250 °C/482 °F.
- 6. When temperatures are at set point, add the next production resin and extrude it at higher screw rotation speed to completely displace the Ultra Purge<sup>™</sup> HT+.
- If possible, replace the screen pack during this 7. phase.
- 8. If contamination persists repeat steps. \* Please note, Ultra Purge<sup>™</sup> HT+ may turn reddish in color after being processed. This is normal part of the cleaning process.







# Ultra Purge<sup>™</sup> HT+ Ready-to-Use Glass-Filled Purging Compound

#### Cleaning Screw and Barrel - Extruder - Material Change - SAME Temperature:

- 1. Make sure the barrel is empty when adding Ultra Purge<sup>™</sup> HT+ in the machine.
- 2. We recommend removing the finest layer of the screen pack. Make sure that the pressure or torque force remains within safety limits when running Ultra Purge<sup>™</sup>.
- Add Ultra Purge<sup>™</sup> HT+ (at least 1.5 times the extruder barrel capacity). 3.
- Extrude at high speed until Ultra Purge<sup>™</sup> HT+ is 4. ejected from the machine.
- 5. Add the next production resin and extrude it at higher screw rotation speed to completely displace the Ultra Purge<sup>™</sup> HT+.
- If possible, replace the screen pack during this 6. phase to speed up the purging process.
- 7. If contamination persists repeat steps.

#### Dosage

Please refer to specific cleaning process.

#### Storage/Handling

Ultra Purge<sup>™</sup> HT+ should be stored in a dry indoor area at room temperature. For further information on storage, handling, hazards, etc. please refer to safety data sheet.

#### Shelf Life 18 months

Packaging Ultra Purge<sup>™</sup> HT+ is available in a variety of package sizes. Please contact Chem-Trend customer service for details.

### **Further Information**

While the technical information and suggestions for use contained herein are believed to be accurate and reliable, nothing stated in this bulletin is to be taken as a warranty either expressed or implied.





Chem-Trend L.P. | 1445 W. McPherson Park | Howell, Michigan Tel 517.546.4520 | U.S./Canada: 800-727-7730 | Fax: 517-548-5370 | ChemTrend.com